

## Landlords

### Please double check Carbon Monoxide and Smoke Detectors compliance

## HUD INSPECTION REQUIREMENTS

It is a best practice to regularly monitor federal, state, and local fire codes for updates to ensure compliance. In addition, the following fire safety requirements are incorporated into HUD's inspection standards:

- The building must provide an alternate means of exit in case of fire, such as fire stairs or **egress** through windows.
- **Smoke detectors** must be in proper working condition and located on each level of the rental unit according to [Housing Quality Standards](#) (HQS) for housing choice voucher (HCV) units and [Uniform Physical Condition Standards](#) (UPCS) for public housing units.
- **Carbon monoxide alarms** or detectors must be installed in all public housing, housing choice voucher, and project-based voucher units by December 27, 2022, as required by HUD in [Notice PIH 2022-01](#).

## NSPIRE - PROPOSED REQUIREMENTS

[National Standards for the Physical Inspection of Real Estate \(NSPIRE\)](#) are HUD's **proposed** inspection standards that would align and replace HQS and UPCS.

NSPIRE fire safety requirements:

- **Method of Egress** includes a safe, continuous, and unobstructed path of travel from any point in the building, unit, or structure to get out of the building.
- **Smoke alarms** must be installed on each level and inside each sleeping area (to conform with National Fire Protection Association (NFPA) Standard 72 – [National Fire Alarm and Signaling Code](#).)
- **Carbon monoxide alarms** must conform with the [2018 International Fire Code](#) (IFC).
- **Fire-labeled doors** must be fully functional and operable.
- **Sprinkler heads** must be functional and unobstructed.